



Paper Calibration Steps:




Hold down the power button on Ozobot for 2 seconds until the LED light flashes white.



Ozobot will move forward and blink green, which means it has successfully calibrated. Start over if Ozobot blinks red.



Quickly Place Ozobot in the middle of the black calibration dot.



Ozobot will calibrate on a black dot (about the size of the robot's base). When drawing, you can create your own black dot with markers.